

7621 Whitepine Road, Richmond, VA 23237 Main 804-743-9401 ° Fax 804-271-6446 www.waypointanalytical.com

10/16/2018

Denali Water Cindy Duenes 2001 Key Street Colton, CA, 92324

Ref: Analytical Testing

Report Number: 18-278-0203 Project Description: Fallbrook

Dear Cindy Duenes:

Waypoint Analytical Virginia, Inc. received sample(s) on 10/5/2018 for the analyses presented in the following report.

The above referenced project has been analyzed per your instructions. The analyses were performed in accordance with the applicable analytical method. Sub-contracted testing is noted on the Sample Summary Table if applicable.

The analytical data has been validated using standard quality control measures performed as required by the analytical method. Quality Assurance, method validations, instrumentation maintenance and calibration for all parameters (NELAP and non-NELAP) were performed in accordance with guidelines established by the USEPA (including 40 CFR 136 Method Update Rule May 2012) and NELAC unless otherwise indicated.

Certain parameters (chlorine, pH, dissolved oxygen, sulfite...) are required to be analyzed within 15 minutes of sampling. Usually, but not always, any field parameter analyzed at the laboratory is outside of this holding time. Refer to sample analysis time for confirmation of holding time compliance.

The results are shown on the attached Report of Analysis(s). Results for solid matrices are reported on an asreceived basis unless otherwise indicated. This report shall not be reproduced except in full and relates only to the samples included in this report.

Please do not hesitate to contact me or client services if you have any questions or need additional information.

Sincerely,

Pauric McGroary Agronomist

Laboratory's liability in any claim relating to analyses performed shall be limited to, at laboratory's option, repeating the analysis in question at laboratory's expense, or the refund of the charges paid for performance of said analysis.

Arizona AZ0629 Florida E871087 New Jersey North Carolina VA011

Pennsylvania South Carolina 68-03109 93007 Virginia 460014





7621 Whitepine Road, Richmond, VA 23237 Main 804-743-9401 ° Fax 804-271-6446 www.waypointanalytical.com

Sample Summary Table

Report Number: 18-278-0203
Client Project Description: Fallbrook

Lab No	Client Sample ID	Matrix	Date Collected	Date Received	Method	Lab ID
63013	Fallbrook	Solids	10/01/2018 12:00	10/05/2018		
63013	Fallbrook	Solids	10/01/2018 12:00	10/05/2018	SM-4500-NH3C	WTN
63013	Fallbrook	Solids	10/01/2018 12:00	10/05/2018	9045D	WTN
63013	Fallbrook	Solids	10/01/2018 12:00	10/05/2018	4500NO3F-2011	WTN
63013	Fallbrook	Solids	10/01/2018 12:00	10/05/2018	6010D	WTN
63013	Fallbrook	Solids	10/01/2018 12:00	10/05/2018	SW-7471B	WTN
63013	Fallbrook	Solids	10/01/2018 12:00	10/05/2018	SM-4500-NH3C-TKN	WTN
63013	Fallbrook	Solids	10/01/2018 12:00	10/05/2018	SM-2540G	WTN

WTN: Waypoint Analytical - TN, Memphis, TN, Certification: #1354

Report Number: 18-278-0203

Account Number: 11035



7621 Whitepine Road, Richmond, VA 23237 Main 804-743-9401 ° Fax 804-271-6446 www.waypointanalytical.com

Send To: Denali Water

Lab Number: 63013

Sample Id: Fallbrook

Cindy Duenes 2001 Key Street Colton, CA 92324

Project: Fallbrook

REPORT OF ANALYSIS

Date Sampled: 10/1/2018 12:00:00

Date Received: 10/05/2018 00:00

Date Reported: 10/16/2018

PARAMETER	RESULT (%)	RESULT (mg/kg)	QUANTITATION LIMIT (mg/kg*)	ANALYST	ANALYSIS DATE/TIME	METHOD
Total Solids *	19.00	190000	100.0	CJR	10/10/2018 16:40	SM-2540G
Moisture *	81.00		100.0	CJR	10/10/2018 16:40	SM-2540G
Total Kjeldahl Nitrogen	5.11	51100	250	CLP	10/10/2018 09:30	SM-4500-NH3C-TKN
Phosphorus	1.69	16900	50.0	JTR	10/11/2018 20:05	6010D
Potassium	0.28	2830	50.0	JTR	10/11/2018 05:28	6010D
Sulfur	0.98	9780	50.0	JTR	10/11/2018 05:28	6010D
Calcium	2.43	24300	100	JTR	10/11/2018 05:28	6010D
Magnesium	0.31	3050	50.0	JTR	10/11/2018 20:05	6010D
Sodium	0.13	1280	250	JTR	10/11/2018 05:28	6010D
Iron		6160	50.0	JTR	10/11/2018 05:28	6010D
Aluminum		4040	50.0	JTR	10/11/2018 05:28	6010D
Manganese		520	5.00	JTR	10/11/2018 05:28	6010D
Copper		1070	2.50	JTR	10/11/2018 20:05	6010D
Zinc		1010	5.00	JTR	10/11/2018 20:05	6010D
Ammonia Nitrogen	0.12	1160	50.0	CLP	10/10/2018 18:00	SM-4500-NH3C
Organic N	4.99	49940	250		10/10/2018 09:30	CALCULATION
Nitrate+Nitrite-N		1730	5.00	JRF	10/12/2018 15:40	4500NO3F-2011

All values are on a dry weight basis except as noted by asterisk. Detection limit on all N series is on a wet basis.

B - Analyte detected in blank H - Beyond Holding Time

Pauric Mc George

Pauric McGroary Agronomist **Report Number:** 18-278-0203

Account Number: 11035



7621 Whitepine Road, Richmond, VA 23237 Main 804-743-9401 ° Fax 804-271-6446 www.waypointanalytical.com

Send To: Denali Water

Lab Number: 63013

Sample Id: Fallbrook

Cindy Duenes 2001 Key Street Colton, CA 92324

Project: Fallbrook

REPORT OF ANALYSIS

Date Sampled: 10/1/2018 12:00:00 **Date Received:** 10/05/2018 00:00

Date Reported: 10/16/2018

PARAMETER	RESULT (%)	RESULT (mg/kg)	QUANTITATION LIMIT (mg/kg*)	ANALYST	ANALYSIS DATE/TIME	METHOD
Cadmium		1.20	1.00	JTR	10/11/2018 20:05	6010D
Chromium		22.2	2.50	JTR	10/11/2018 05:28	6010D
Nickel		21.2	2.50	JTR	10/11/2018 20:05	6010D
Lead		10.1	3.00	JTR	10/11/2018 05:28	6010D
Arsenic		<5.00	5.00	JTR	10/11/2018 20:05	6010D
Mercury		0.947	0.0151	KKM	10/10/2018 12:15	SW-7471B
Selenium		6.98	5.00	JTR	10/11/2018 20:05	6010D
pH *	5.3			JSL	10/11/2018 07:36	9045D
Molybdenum		15.2	2.50	JTR	10/11/2018 05:28	6010D

Comments:

All values are on a dry weight basis except as noted by asterisk. Detection limit on all N series is on a wet basis.

B - Analyte detected in blank

H - Beyond Holding Time

Pauric Mc George



7621 Whitepine Road, Richmond, VA 23237 Main 804-743-9401 ° Fax 804-271-6446 www.waypointanalytical.com

Cooler Receipt Form

Customer Number: 11035 **Denali Water** Customer Name: 18-278-0203 Report Number: **Shipping Method** Fed Ex Other: US Postal UPS Client Courier Thermometer ID: Shipping container/cooler uncompromised? Yes () No Number of coolers received 1 Yes O No Not Required Custody seals intact on shipping container/cooler? Yes Not Required Custody seals intact on sample bottles? () No Chain of Custody (COC) present? Yes \bigcirc No COC agrees with sample label(s)? Yes () No COC properly completed Yes O No Samples in proper containers? Yes () No Sample containers intact? Yes O No Sufficient sample volume for indicated test(s)? Yes \bigcirc No All samples received within holding time? Yes O No Cooler temperature in compliance? Yes No Cooler/Samples arrived at the laboratory on ice. Yes No Samples were considered acceptable as cooling process had begun. Yes O No N/A Water - Sample containers properly preserved Water - VOA vials free of headspace Yes No N/A Yes Trip Blanks received with VOAs () No N/A N/A Soil VOA method 5035 - compliance criteria met Yes \bigcirc No High concentration container (48 hr) Low concentration EnCore samplers (48 hr) High concentration pre-weighed (methanol -14 d) Low conc pre-weighed vials (Sod Bis -14 d) Special precautions or instructions included? () Yes No Comments:

Date & Time: 10/05/2018 13:08:02

Signature: Brandi Watson

